


## QUALCOMM Incorporated Page 4 of 4 010110; EV 074 585 551 US Rotem Cooper





	<b>*</b>	
	ACQUISITION/REGISTRATION FAILURE	AVOIDANCE_DURATION
	Unable to Acquire Pilot Signal	30 seconds
204	- Unable to Acquire Synchronization Channel	30 seconds
90;	- Unable to Acquire Paging Channel	30 seconds
80;	- Registration Rejected By Wireless Communications System	2 minutes
01:	Mobile Station Has Experienced Frequent Signal Fading	2 minute
72 -	Protocol Mismatch	5 minute
	- Invalid Redirection	1 minute

FIG.